

TEST TOOLING MADE EASY

Whether you're testing conventional packages like QFNs and BGAs, or emerging 2.5D and 3D packages, you're only as successful as your test floor equipment. This session's presenters span the spectrum of tooling issues beginning with a method for 3D package handling through the integration of complex technologies. Next, you'll learn how to prevent semiconductor test system coolant leakage by implementing a hazardous warning system. Operator error in manual test handlers comes under scrutiny thanks to a failure analysis investigation in QFN packages. Lastly, we take a look at cost saving through homogenous spring pin tip implementation in a high volume manufacturing (HVM) environment.

3D Package Handling: A Simple Case of Integrating Complex Technologies

Zain Abadin—Advantest America, Inc.

Innovative Way to Prevent Semiconductor Test Tester Coolant Leakage with Hazardous Warning System

Yee Wei Tiang—Intel (Malaysia)

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

M.P. Divakar, PhD—Stack Design Automation

Cost Saving Through Homogenous Spring Loaded Pin Tip Implementation in High Volume Manufacturing (HVM) Environment

Chin Siang (David) Chew, Nithya Nandhan Subramaniam—Intel Technology
Chin Chien Tee—Interconnect Devices, Inc.



This Paper

COPYRIGHT NOTICE

The paper(s) in this publication comprise the Proceedings of the 2013 BiTS Workshop. The content reflects the opinion of the authors and their respective companies. They are reproduced here as they were presented at the 2013 BiTS Workshop. This version of the papers may differ from the version that was distributed in hardcopy & softcopy form at the 2013 BiTS Workshop. The inclusion of the papers in this publication does not constitute an endorsement by BiTS Workshop, LLC or the workshop's sponsors.

There is NO copyright protection claimed on the presentation content by BiTS Workshop, LLC. (Occasionally a Tutorial and/or TechTalk may be copyrighted by the author). However, each presentation is the work of the authors and their respective companies: as such, it is strongly encouraged that any use reflect proper acknowledgement to the appropriate source. Any questions regarding the use of any materials presented should be directed to the author(s) or their companies.

The BiTS logo and 'Burn-in & Test Strategies Workshop' are trademarks of BiTS Workshop, LLC. All rights reserved.

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

MP Divakar, PhD
Stack Design Automation



2013 BiTS Workshop
March 3 - 6, 2013



Content

- Background
- Summary of Failed Packages
- Failure Analysis
- Finite Element Analytical Investigations
- Findings
- Conclusions
- References

Background

- A series of failures were observed on a Digital Controller product packaged in 6x6mm 40-lead QFN during High Temperature Operating Life (HTOL) qualification tests run at two test houses, A (TH-A) and B (TH-B).
- Test program began at TH-B and then moved to TH-A.
- Failure modes ranged from loss of continuity to intermittency and opens.
- Packaged parts were tested on a Teradyne J750 mixed signal tester with manual handler.
- All parts were functional prior to the HTOL tests.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

3

Background

- A total of failed 9 parts (6 at TH-A and 3 at TH-B) were found;
- One sample was found failing functional tests prior to HTOL.
- A summary of failed parts is shown in the following table.
- Failures were first observed at TH-B. Due to this and other reasons, the test program was moved to TH-A.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

4

Summary of Failed Packages

HTOL Start Date	Location	Lot #	Sample Size	# of Fails	Failure Symptom	Failure Cause	Tot # of Cracked Die
20-May-xx	TH-A	E10007	40 Units 1 Lot	3 1 at 84, 1 at 174 & 1 at 500 Hr	2 Functional, 1 Continuity	EOS, ESD & Si Damage	None
20-May-xx	TH-A	E10002	40 Units 1 Lot	7 all at 212 Hr	Continuity	1 EOS & 6 Die Crack	6
19-Aug-xx	TH-B	E10010	80 1 Lot	1, at 168 Hr	Functional	Die Crack Pkg#269	1
19-Aug-xx	TH-B	E10009	79 1 Lot	1 at 500 Hr	Functional	Die Crack Pkg#101	1
19-Aug-xx	TH-B	E10008	80 1 Lot	NONE	Functional	Die Crack Pkg#11	1

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

5

Observations

- All failed packages were examined visually, using X-Ray imaging and Confocal Scanning Acoustic Microscopy (CSAM). These yielded no discernable clues to the cause/s of failure.
- External visual examination at 100X magnification showed that some of the package pads at the bottom had indentation marks left by the top side of probe pins from the socket.
- The indentations were biased more toward the side with Pin-1 location than the other sides.
- Further, some indentation marks were also seen in the middle of the package paddle.
- All packages were de-lidded for closer inspection.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

6

Observations

- Three of the packages showed signs of electrical overstress and electrostatic discharge near some of the pads on the dice.
- These failures were on a side perpendicular to Pin-1 location.
- Six of the packages showed cracks in the dice, shown in next slides. Majority of the cracks were on the side where Pin-1 is located.
- Two samples showed cracks close to the edge opposite to that of Pin-1.
- One die showed smaller crack along a side perpendicular to that of Pin-1.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

7

Observations


- Socket was disassembled, contact block and the probe pin carrier were separated.
- Probe pins were removed from the carrier and position of each probe pin in the carrier was mapped with respect to Pin-1 (shown after next slide).

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

8

Cracked Die Images From Units Tested at TH-A




3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

9

Cracked Die Images From Units Tested at TH-B



3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

10

Observations...

- Device Under Test (DUT) circuit board was closely examined.
- Attention was focused on the test socket and the manual handler.
- Test socket was removed from the DUT board and disassembled.
- Socket cavity was visually examined at 100X magnification.
- Looking down the socket cavity, some of the probe pins appeared bent.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

11

Observations...


- Socket was disassembled, the contact block and the probe pin carrier were separated.
- Probe pins were removed from the carrier and the position of each probe pin in the carrier was mapped with respect to Pin-1 (shown after next slide)
- There were many bent probe pins (shown next slide) with inflection points near the weep hole of probe pins in sockets from both test houses.
- Socket from TH-A also had some missing probe pins that were designed to interface with the package paddle.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

12

Observed Damage in Probe Pins from TH-B Sockets






3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

13

Damaged Probe Pin Locations in Test Socket at TH-A



RED Circles & oval denote sites with bent probe pins
 BLUE circles denote missing probe pins
 (TH-A)

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

14

Observations...

- Next, the test socket lid assembly was examined. This design uses secondary actuation with a star-shaped handle used to actuate calibrated and evenly-distributed pressure on the chip package's top surface in open and close position, shown in next slide.
- Further, the open vs. close positions and the angular range of travel (most designs use 90 or 180deg) thereof in the star-shaped handle is controlled by a set screw, shown next slide.
- Applied pressure is transferred to the package top using a spring-activated plunge screw whose travel is set based on the package height and the range of travel designed for the probe pins.
- This range is the difference in height between assembled vs. loaded states of the probe pins, shown next slide.
- Closer observation of the star-shaped socket lid handle and the plunge screw showed wear on the surfaces. It appeared that the test operators removed the set screw so that the socket handle traveled beyond the range its design for.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

15

Observations...



- Further, there were clear signs of over-torque in the socket handle at the slot where 'open' & 'close' positions are marked by prying it with a screw driver.
- It appeared that the test operators did this to address intermittency of spring pin contacts.
- It was postulated that the die cracking was induced by over-torque of the socket handle.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

16

Observed Damage in Test Socket at TH-A



Ref: Ila Pal, 2005


Socket Handle Wear (most likely caused by torquing with a metallic object such as a screw driver; the wear marks continue on to the plunge screw as circled above and hit the opposite wall of the plunge screw, shown in the previous page)

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

17

Observed Damage in Test Socket at TH-A



Socket Plunge Screw Wear and Missing Set Screw

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

18

Failure Analysis

- A failure analysis study was undertaken to validate over-torque of socket handle as the root cause of initiating cracks in the die.
- Package assembly process starting with the backend process at the Semi fab was also reviewed.
- These included backgrinding and polishing which have higher likelihood of building up residual stresses, initiate defects and induce microcracks in the wafer due to process-related stresses.
- Wafer dicing process (using blade saw) was reviewed. Examination of the die edges indicated chipouts and crack initiation as the edges of dice.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

19

Failure Analysis

- Chipouts and partial cracking in the Silicon die may have exacerbated the cracking process in the packaged die.
- A finite element simulation replicating the overloading in test sockets was undertaken to estimate the Silicon stresses.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

20

Finite Element Analytical Investigations

- Based on the deformation patterns observed in the probe pins, their locations and the observed crack patterns in the dice, it was theorized that over torquing led to uneven loading of the chip packages.
- The kinematic model approximating the displaced position of a model is shown next slide (left side of the model represents the side with Pin-1).
- The finite element model captures the lead frame, die attach, Silicon Die, molding compound and the probe pins represented by spring elements.
- A 2D FE model was used but the same approach can be applied to 3D models.
- Based on the datasheet for the probe pins, a spring constant model was developed in a separate FE analysis.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

21

Finite Element Analytical Investigations


- Spring constants were separately established for undamaged and damaged probe pins.
- Spring constants were separately established for undamaged and damaged probe pins.
- A prescribed rotation ranging from 1 to 5 degrees was applied to the tip of probe pins and the corresponding deformed geometry was used to develop stiffness model representing damaged probe pins.
- The FE model uses imposed deformation up to 0.030mm over and above the maximum range of travel for the damaged probe pins.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

22

Deformation Mechanism at Socket Overloading



Deformation mechanism demonstrating observed overloading in test sockets




Kinematic model for overloading in test sockets

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

23


Modeling Socket Overloading



Probe Pin

Probe Pins

Probe Pin





FE Model without spring models for probe pins

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

24

Data Sheet: Probe Pins




Probe Specifications

Minimum Device Pitch: 0.50 (.020)
 Signal Path Length: 2.37 (.093)
 Force per Contact: 27 grams (0.96 oz.) @ 0.30 (.012) travel
 Device Compliance: 0.15 (.006)
 DUT Board Compliance: 0.15 (.006)
 Maximum Compliance: 0.38 (.015)
 Operating Temperature: -55° C to 150° C
 Insertions: >500,000

Materials

Barrel: Full-hard beryllium copper, Endura plating
Spring: Stainless steel, gold plated - 0.96 oz. spring Music wire, gold plated - 1.12 oz. spring
Plungers: Full-hard beryllium copper, gold plated




101266 Endura Series Semiconductor Probe - Minimum Device Pitch: 0.50mm
 (Dimensions in mm, red in inches)

3/2013


Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

25


Modeling of the Probe Pins for FE Simulations



Dimensions in mm



Pogo Pin End Deflection






3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

26

Probe Pin Models –Intact & Damaged



3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

27

Findings

- As shown in the next two slides, the evolution of stresses due to increasing displacements on probe pins show von Mises stresses in Silicon die exceeding 600MPa.
- When imposed displacements were applied in the middle (package paddle) area in addition to the left edge the stress magnitudes were even higher.
- Research investigations documented so far clearly indicate a very significant drop in fracture strength of Silicon due to dicing chipouts, divots and backgrind-induced defects.
- In some cases the drop in fracture strength can be as high as 50%.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

28

Findings

- Appropriate compression of the probe pins is critical in the design of test sockets for successful and repeatable probe pin performance.
- A change in process incorporating double-saw for wafer dicing and the corresponding DOE run at Amkor has revealed no chipouts and dicing cracks.
- Subsequent HTOL tests and corrected sockets showed no failures.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

29

Evolution of Stresses in Package w/Imposed Displacements

Displacement
Loading


@ 0.006 mm

@ 0.012 mm

@ 0.017 mm

@ 0.024 mm

@ 0.030 mm



3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

30

Stresses in Package at 0.030mm Loading



Stress contours in package using probe pin displacements (in MPa)



Stress contours in Silicon die using probe pin displacements (in MPa)

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

31

Conclusions

- Analytical and experimental investigations were conducted to establish the root cause of die cracking in a Digital Controller in 6x6 40-Lead QFN packages.
- Data gathered overwhelmingly point to overloading in the test sockets for further investigation.
- After examining the test sockets used at the two test labs, it was possible to map the damage locations and correlate them to the observed crack patterns in the failed units.
- Analytical models were proposed to simulate the overloading in test sockets based on the observed damages in the sockets.
- Results of finite element simulations using the proposed models indicate that the stresses in die surpass the tensile strength of Silicon using two separate approaches.

3/2013

Die-Cracking Failure Analysis of QFN Packages in Manual Test Handler

32

References

- Desmond Y.R. Chong, W.E. Lee, B.K. Lim, John H.L. Pang & T.H. Low. "Mechanical Characterization In Failure Strength Of Silicon Dice," IEE 2004 Inter Society Conference on Thermal Phenomena, pp 203-210.
- J.D. Wu , C.Y. Huang, C.C. Liao. "Fracture strength characterization and failure analysis of silicon dies," Microelectronics Reliability 43 (2003), pp 269–277.
- C. Bohm, T. Hauck, A. Juritza & W.H. Müllertest. "Weibull Statistics of Silicon Die Fracture," 2004 Electronics Packaging Technology Conference, pp 782-786.